

Released Engineering Change Notice

Product	Wizard 3
---------	----------

Title	Update rear connector PCB's to plated through hole
-------	--

Date	1 st Feb 2007
------	--------------------------

Details Of Change

To update the following connector PCB's to plated through hole:
 AG6316 - Wizard 316
 AG6314 - Wizard 314
 AG6317 - Wizard 312
 AG6312 - Wizard 320s

Reason for change

There have been reported failures of the solder joints on the XLR and Jack connectors.

This ECN supersedes ECN No.		
	Related ECNs	

Post Implementation Ser No		
Serial Number	Model	Date
	Wizard 3	Feb 07

Serial Number	Model	Date

Additional Information