

Released Engineering Change Notice

Product	ML3000
---------	--------

Title	Value change to resistors R41 and R100 to68K.
-------	---

Date	21 ST JANUARY 2008
------	-------------------------------

Details Of Change
Value change to resistors R41 and R100 to 68K.

Reason for change
Group assign leds too bright.

This ECN supersedes ECN No.	Related ECNs
-----------------------------	--------------

Post Implementation Ser No		
Serial Number	Model	Date
ML300048002586	ML3000	

Serial Number	Model	Date

Additional Information
FYI- note that led`s 13 & 14 originally were type AE4041- now replaced with type AE6901 which require this resistor change.

Brief details:

Turn off 'Protect Form' lock to complete. Insert rows if required or attach more detailed documents in 'Additional Information' table below.

Assembly	Designator	Added (y)	Deleted (y)	Moved (y)	From (y)	Part no./description	To (y)	Part no./description
002-745	R41,100				Y	AC0101 RES CARBON 6K8 1/4W 5%	Y	AC0062 RES CARBON 68K 1/4K 5%

R41 & R100 to become 68K (AC0062)

SMT/AI/RI Program and Barcode Issue updates:

Assy no.	Part no.	SMT/AI/RI Program and Barcode Issue updates		
		Previous	to	New
002-745	AG4454		to	Iss.7
			to	