ALLEN&HEATH



WARNING — HIGH VOLTAGES

Power Supply Unit (PSU) work should only be carried out by qualified personnel.

We recommend that you use an approved Allen & Heath service centre for all power supply work.

Please contact your local Allen & Heath distributor for more details.

http://www.allen-heath.com/

SUPPLY ON FUSE RATING : 1 A AT 120V 0,5A AT 240V 24 V 2SD 234 EC 470 R NO 2000 m 2000 ju 40V ZD Z OV 7777

STEREO A.D.T. UNIT
POWER SUPPLY