

## High Sierra "System Extension Blocked"

Since OS 10.13 High Sierra, Apple introduced a new security feature which requires approval when trying in to install and use third-party drivers, this has however led to some cases where interfaces are not being recognised, because they have not been approved.

When the installation of the driver was complete the following message should have been displayed; "System Extension Blocked". Although, in some cases this has not shown up. Never the less, you will still need to authorise the driver.

These drivers must be authorised within half an hour of installation otherwise you will need to re-install. so, in which case the first thing you need to do is to uninstall the driver by running the OS X driver remover .app then reset the Mac.

So, whether you get the "System Extension Blocked" or not, please go to System preferences/security & privacy, you should then see a message...

### **"System software from developer ????? was blocked"**

Click "Allow". You should now be in business! If the device is not recognised, disconnect then reconnect the device.