

**Released Engineering Change Notice**

|         |                                 |
|---------|---------------------------------|
| Product | <b>ML3000</b>                   |
| Title   | <b>GROUP AUX</b>                |
| Date    | <b>25<sup>th</sup> May 2005</b> |

|                          |   |
|--------------------------|---|
| <b>Details Of Change</b> | <b>CHANGE HOLE SIZE OF CONNECTOR ON FADER BREAK OFF</b> |
|--------------------------|---|

|                          |  |
|--------------------------|--|
| <b>Reason for change</b> | <b>TO IMPROVE FIT IN MANUFACTURING</b> |
|--------------------------|--|

|                             |  |  |  |
|-----------------------------|--|--|--|
| This ECN supersedes ECN No. | <table border="1" style="width: 100%;"> <tr> <td style="width: 50%;"></td> <td style="width: 50%;"></td> </tr> </table> Related ECNs |  |  |
|                             |  |  |  |

|                                   |        |          |
|-----------------------------------|--------|----------|
| <b>Post Implementation Ser No</b> |        |          |
| Serial Number                     | Model  | Date     |
|                                   | ML3000 | Nov 2005 |
|                                   |        |          |
|                                   |        |          |

|               |       |      |
|---------------|-------|------|
| Serial Number | Model | Date |
|               |       |      |
|               |       |      |

|                               |   |
|-------------------------------|---|
| <b>Additional Information</b> | <b>Up-issue AG4452 pcb to issue 3.2</b> |
|-------------------------------|---|