

**Released Engineering Change Notice**

Product	<b>IDR-10</b>
Title	<b>Carrier AA5537- Up-issue to issue 3</b>
Date	<b>11/07/2007</b>

Details Of Change
<b>Two additional 8mm slots to be added to metalwork.</b>

Reason for change
<b>Slots required for clearance of fan side plates.</b>

This ECN supersedes ECN No.	<input type="text"/>	<input type="text"/>
	Related ECNs	

Post Implementation Ser No	<input type="text"/>
Serial Number	Model
	<b>IDR-10</b>
	<b>July 07</b>

Serial Number	Model	Date

Additional Information										
<b>Metalwork AA5537 to be up-issued to issue 3.</b>										
<b>Macpac Pcb/Metalwork/Drawing Issue updates:</b>										
Turn off 'Protect Form' lock to complete. Insert rows if required.										
<table border="1"> <tr> <td>Assy no.</td> <td>Part no.</td> <td colspan="3">Pcb/Metalwork/Drawing Issue updates (from _ to _)</td> </tr> <tr> <td><b>003-534</b></td> <td><b>AA5537</b></td> <td></td> <td>to</td> <td><b>Issue 3</b></td> </tr> </table>	Assy no.	Part no.	Pcb/Metalwork/Drawing Issue updates (from _ to _)			<b>003-534</b>	<b>AA5537</b>		to	<b>Issue 3</b>
Assy no.	Part no.	Pcb/Metalwork/Drawing Issue updates (from _ to _)								
<b>003-534</b>	<b>AA5537</b>		to	<b>Issue 3</b>						