

**Released Engineering Change Notice**

Product	Xone 42
Title	Slave pcb AG6994 capacitor value changes
Date	Nov 2007

Details Of Change
<p>On the slave PCB, AG6994_1 change capacitors C20, 21, 22, 23 from 100N (AF2851) to 330N (AF5070)</p> <p>Circuit updated to 1.2.</p>

Reason for change
<p>Excessive voltage transition on VCA DC mix amps causing noise on mixer outputs when crossfader contour control at max.</p>

This ECN supersedes ECN No.		Related ECNs
-----------------------------	--	--------------

Post Implementation Ser No		
Serial Number	Model	Date
X42/220080529	Xone 42	Nov 07

Serial Number	Model	Date

Additional Information