

# ALLEN & HEATH



## **WARNING – HIGH VOLTAGES**

Power Supply Unit (PSU) work should only be carried out by qualified personnel.

We recommend that you use an approved Allen & Heath service centre for all power supply work.

Please contact your local Allen & Heath distributor for more details.

<http://www.allen-heath.com/>

RPS 3 TO RPS 3B MODS

REMOVE R.15, R.6, R.8, R.17

REPLACE R.7, R.16. WITH LINK

REPLACE R.9, R.18 WITH 2X 0.33R //

REPLACE 4A FUSES WITH 5A

RETEST AS NORMAL

ALSO CHECK SHORT CIRCUIT I = 3.8 - 4.0 AMPS.

DO NOT SHORT CIRCUIT FOR > 5 SECONDS.

RR 22-1-90

~~MC 0552~~