


-  Refer to www.allen-heath.com for instructions on how to update the dLive firmware and important notes about the update.

V1.41 March 2017

Maintenance release

Improvements

- Addition of a 3-band mode to the Dyn8 multiband compressor.
- Per band In/Out buttons in the Dyn8 multiband compressor now fully bypass the multiband processing, thus avoiding phase distortion.
- Improvements to system responsiveness and management of network traffic.

Fixes

- ID3965 User Scenes could be recalled at login without notification.
- ID3990 Scene descriptions could not be edited.
- ID3959 The Pan mode for 5.1 routing could reset after restarting the system.
- ID3933 DCA Spills could be erroneously activated by Scene recalls.
- ID3994 The Dyn8 sidechain source would not reset correctly after a stereo config change.
- ID3934 Director would not control preamp gain from the I/O screen socket popup.
- ID3954, 3951, 3943 Fixes to Virtual SoundCheck mode.

Several other minor fixes and improvements.

Known issues

- ID522 Main LR cannot be ganged when set to individual fader strips.
- ID3931 Connection to DX32 Expanders is occasionally lost after many hours of continuous operation. We recommend restarting the system every day to avoid audio dropouts.
- ID3655 dLive Director has performance issues on OS X 10.10 Yosemite seemingly caused by the trackpad behaviour. We recommend using an external mouse as a workaround or updating your OS.

V1.40 January 2017

Feature release

New features

- Virtual Soundcheck mode
- DCA spills

- Dyn8 insert-able dynamic engine
- DEEP Processing Peak Limiter 76
- Multistage ducking
- Dimension Chorus effect
- 3rd screen view on VGA output
- Support of dLive C Class products and fibreACE audio networking card

Several other improvements and fixes – please refer to [V1.40 Release Notes](#) for details on fixes and improvements.

V1.31 September 2016

Maintenance release

Several fixes – please refer to [V1.31 Release Notes](#) for details on fixes and improvements.

V1.30 July 2016

Feature release

New features

- Support for IP6 and IP8 Remote Controllers
- Support for Waves V3 and gigaACE audio networking cards
- MixRack and Surface Network settings are now available in Director when in online mode

Several fixes – please refer to [V1.30 Release Notes](#) for details on fixes and improvements.

V1.21 June 2016

Maintenance release

Several fixes – please refer to [V1.21 Release Notes](#) for details on fixes and improvements.

V1.20 June 2016

Feature release

New features

- dLive Director software for Mac and Windows
- Dual-Stage Valve Preamp
- 5.1 Main mode
- 8 Mute Groups
- User defined meter ballistics and Peak Hold
- Multi PAFL Bus

Several other improvements and fixes – please refer to [V1.20 Release Notes](#) for details on fixes and improvements.

V1.11 March 2016

Maintenance release

Several fixes – please refer to [V1.11 Release Notes](#) for details on fixes and improvements.

V1.10 January 2016

Feature release

New features

- **DX32 support** – Up to 3 DX32 modular I/O expanders can be connected to a dLive system.
- **ME-1 names and stereo links** – Channel names and stereo links are now communicated over the Monitor port to connected ME-U and / or ME-1 units.
- **I/O Port card discovery and settings** – Cards fitted to the I/O Ports are now listed on the relevant screens and their options displayed.

Several fixes – please refer to [V1.10 Release Notes](#) for details on fixes and improvements.

V1.03 December 2015

Maintenance release

Several fixes – please refer to [V1.03 Release Notes](#) for details on issues fixed.

V1.02 November 2015

Maintenance release

New features and improvements

ID1225 PAFL Delay time increased, now up to 170ms.

ID1149 Fader calibration added.

ID1279 Contextual Help added.

Several fixes – please refer to [V1.02 Release Notes](#) for details on issues fixed.

V1.0 September 2015

This was the first public release of dLive firmware.