

## Custom Control Release Notes

**V1.2.5**

📌 Refer to [www.allen-heath.com](http://www.allen-heath.com) for instructions on how to update the Avantis firmware and important notes about the update.

### V1.2.5 December 2021

Maintenance Release

**Fixes:**

ID355, ID372 Connecting an earlier version of the Custom Control app to a unit with a V1.2.4 Config would reset all faders to 0dB and could display the wrong state for buttons and LEDs.

📌 We recommend that any Config created in V1.2.4 is re-saved in V1.2.5 and re-uploaded to the unit/s to prevent the occurrence of this bug.

ID348, ID350 Improved efficiency and memory usage of large Configs to reduce connection time and prevent freezes or crashes on low-performance hardware.

### V1.2.4 July 2021

Feature Release

**New Features:**

- Kiosk version for Android now supports CC-7 and CC-10 touch panels

**Fixes:**

ID328 Under certain circumstances, changing the number of tabs of a tab container could cause Custom Control editor to crash

ID324 Fader control sensitivity improved

### V1.1.1 August 2020

Maintenance Release

📌 Layouts created in V1.1.0 with AHM Zone post-compressor/post-fader meter types should be re-saved in V1.1.1 with the correct meter tap-off points selected.

**Fixes:**

ID321 Text labels for Meters and Chromatic Meters are not editable in V1.1.0

ID322 AHM Zone metering not displaying correctly when using Post-Compressor and Post-Fader meter types in V1.1.0

**Known Issues:**

ID313 Dynamic Labels not working with Avantis mixers – will be resolved in future Avantis firmware (V1.10)

- ID317      Setting an invalid send level in Custom Control triggers warning triangle and error log entries on Avantis mixers – will be resolved in future Avantis firmware (V1.10)

## **V1.1.0    July 2020**

### Feature Release

#### **New Features:**

- AHM-64 compatibility
- Avantis compatibility
- Text Colour option added for Button, LED and Source Selector widgets

#### **Fixes:**

- ID286      Gain Reduction meter shows as unavailable on Stereo Group, Stereo Aux and Stereo Matrix
- ID294      Changing colour properties of multiple Chromatic Meters does not work as expected
- ID296      Gain Reduction meter on the right (R) channel of stereo inputs does not update correctly
- ID300      Custom Control app doesn't work with WiFi Mobile Data Assist

## **V1.00    June 2019**

This is the first public release of Custom Control.