

Custom Control Release Notes

V1.2.6

❗ Refer to www.allen-heath.com for instructions on how to update the Avantis firmware and important notes about the update.

❗ We recommend that any Config created in V1.2.4 is re-saved in V1.2.5 or higher and re-uploaded to the unit/s.

V1.2.6 March 2022

Maintenance Release

Fixes:

- ID382 Losing or disabling the network connection could result in the app crashing in some cases.
- ID392 Restarting an AHM processor via System Manager could crash the Custom Control app.

V1.2.5 December 2021

Maintenance Release

Fixes:

- ID355, ID372 Connecting an earlier version of the Custom Control app to a unit with a V1.2.4 Config would reset all faders to 0dB and could display the wrong state for buttons and LEDs.

❗ We recommend that any Config created in V1.2.4 is re-saved in V1.2.5 or higher and re-uploaded to the unit/s to prevent the occurrence of this bug.

- ID348, ID350 Improved efficiency and memory usage of large Configs to reduce connection time and prevent freezes or crashes on low-performance hardware.

V1.2.4 July 2021

Feature Release

New Features:

- Kiosk version for Android now supports CC-7 and CC-10 touch panels

Fixes:

- ID328 Under certain circumstances, changing the number of tabs of a tab container could cause Custom Control editor to crash
- ID324 Fader control sensitivity improved

V1.1.1 August 2020

Maintenance Release

ⓘ Layouts created in V1.1.0 with AHM Zone post-compressor/post-fader meter types should be re-saved in V1.1.1 with the correct meter tap-off points selected.

Fixes:

- ID321 Text labels for Meters and Chromatic Meters are not editable in V1.1.0
- ID322 AHM Zone metering not displaying correctly when using Post-Compressor and Post-Fader meter types in V1.1.0

Known Issues:

- ID313 Dynamic Labels not working with Avantis mixers – will be resolved in future Avantis firmware (V1.10)
- ID317 Setting an invalid send level in Custom Control triggers warning triangle and error log entries on Avantis mixers – will be resolved in future Avantis firmware (V1.10)

V1.1.0 July 2020

Feature Release

New Features:

- AHM-64 compatibility
- Avantis compatibility
- Text Colour option added for Button, LED and Source Selector widgets

Fixes:

- ID286 Gain Reduction meter shows as unavailable on Stereo Group, Stereo Aux and Stereo Matrix
- ID294 Changing colour properties of multiple Chromatic Meters does not work as expected
- ID296 Gain Reduction meter on the right (R) channel of stereo inputs does not update correctly
- ID300 Custom Control app doesn't work with WiFi Mobile Data Assist

V1.00 June 2019

This is the first public release of Custom Control.