

Released Engineering Change Notice

Product	W3 12/16
---------	-----------------

Title	New Effects pcb AG6551 Mk2
-------	-----------------------------------

Date	15th May 2006
------	---------------------------------

Details Of Change	AG6551 PCB W3 EFFECTS MK2
-------------------	----------------------------------

Reason for change	Component obsolescence
-------------------	-------------------------------

This ECN supersedes ECN No.	See below	Related ECNs
-----------------------------	------------------	--------------

Post Implementation Ser No		
Serial Number	Model	Date
All	W31222	Oct 06
	W31622	Oct 06

Serial Number	Model	Date

Additional Information	A&H RECNs 1272, 1273, 1288, 1289, 1290
------------------------	---

Details Of Change

AG6551 PCB W3 EFFECTS MK2 replaces AG5584 PCB W3 EFFECTS (new parts list, new assy 003-567)
003-568 PCB ASSY W3 16/12 AUX YELLOW LED replaces 003-168 (i.e. Yellow leds replace Green leds)
003-573 PROG IC W3 FX (AE5496) (NEW FX) replaces 003-201 (i.e. new program for AE5496 IC SMD EPROM OTP 27C512)
003-567 PCB ASSY W3 EFFECTS MK2 replaces 003-220 PCB ASSY W3 EFFECTS

Brief details:

Assy	Desig	Added (y)	Deleted (y)	Part no./description
003-220			Y	PCB ASSY W3 EFFECTS
003-567		Y		PCB ASSY W3 EFFECTS MK2 (MOTOR
003-168			Y	PCB ASSY W3 16/12 AUX
003-568		Y		PCB ASSY W3 16/12 AUX YELLOW L

Macpac Pcb/Metalwork/Drawing Issue updates:

Assy no.	Part no.	Pcb/Metalwork/Drawing Issue updates (from _ to _)		
003-567			to	0100
003-568			to	0100
	AG5584		to	Iss 1
			to	

It is important to note that new effects assembly is used in conjunction with up-issued front panel and up-issued led assembly (yellow led's).

At same time the up-issued user guide must be included.