

Released Engineering Change Notice

Product	iDR4&8
Title	IDR CPU PCB AG4481 - tented vias
Date	05/03/2007

Details Of Change
update AG4481 to have tented vias and fiducial marks on the bottom of the PCB.

Reason for change
This board is now tested on the AOI machine

This ECN supersedes ECN No.		Related ECNs
-----------------------------	--	--------------

Post Implementation Ser No		
Serial Number	Model	Date
	iDR4&8	Aug 07

Serial Number	Model	Date

Additional Information																									
<p>2 Fiducials added to bottom side, Bottom side vias tented.</p> <p>SMT/AI/RI Program and Barcode Issue updates: Turn off 'Protect Form' lock to complete. Insert rows if required.</p> <table border="1"> <tr> <td>Assy no.</td> <td>Pcb no.</td> <td colspan="3">SMT/AI/RI Program and Barcode Issue updates (from _ to _)</td> </tr> <tr> <td>003-006</td> <td>AG4481</td> <td></td> <td>to</td> <td>30060300</td> </tr> <tr> <td>003-114</td> <td>AG4481</td> <td></td> <td>to</td> <td>31140300</td> </tr> </table> <p>Macpac Pcb/Metalwork/Drawing Issue updates: Turn off 'Protect Form' lock to complete. Insert rows if required.</p> <table border="1"> <tr> <td>Assy no.</td> <td>Part no.</td> <td colspan="3">Pcb/Metalwork/Drawing Issue updates (from _ to _)</td> </tr> <tr> <td></td> <td>AG4481</td> <td>2</td> <td>to</td> <td>3</td> </tr> </table>	Assy no.	Pcb no.	SMT/AI/RI Program and Barcode Issue updates (from _ to _)			003-006	AG4481		to	30060300	003-114	AG4481		to	31140300	Assy no.	Part no.	Pcb/Metalwork/Drawing Issue updates (from _ to _)				AG4481	2	to	3
Assy no.	Pcb no.	SMT/AI/RI Program and Barcode Issue updates (from _ to _)																							
003-006	AG4481		to	30060300																					
003-114	AG4481		to	31140300																					
Assy no.	Part no.	Pcb/Metalwork/Drawing Issue updates (from _ to _)																							
	AG4481	2	to	3																					