

Released Engineering Change Notice

Product	W312M
Title	W312M Distribution AG6765 Up-issue to issue 2
Date	29/03/07

Details Of Change
Distribution UP-ISSUE FROM AG6765_1 TO AG6765_2 ASSY 003-669

Reason for change
Allow space to use cutting machine, removal of ground between molex's, added SYS-LINK PFL solder pin.

This ECN supersedes ECN No.	<input type="text"/>	<input type="text"/>
	Related ECNs	

Post Implementation Ser No	
Serial Number	Model
	W312M
	Date
	May 07

Serial Number	Model	Date

Additional Information				
Assy no.	Part no.	Pcb/Metalwork/Drawing Issue updates (from _ to _)		
003-669	AG6765	Issue 1	to	Issue 2
Assy no.	Pcb no.	SMT/AI/RI Program and Barcode Issue updates (from _ to _)		
003-669			to	36690200