

Released Engineering Change Notice

Product	PA-CP
Title	IDC header clamp AL6912 no longer used
Date	23/09/2010

Details Of Change
<p>IDC header clamp AL6912 no longer used. For all versions of PA122-CP and PA202-CP remove AL6912 CLAMP IDC HEADER A&H from the front edge of the main harness <u>only</u>.</p> <p>003-497 MAIN ASSY PA 122-CP – Remove x11 AL6912 CLAMP IDC HEADER A&H (see attached photos) 003-499 MAIN ASSY PA 202-CP – Remove x19 AL6912 CLAMP IDC HEADER A&H (same as PA122 , plus additional inputs)</p>

Reason for change
Reports of clamps falling off during transit due to contact with base screen plate.

This ECN supersedes ECN No.		Related ECNs
-----------------------------	--	--------------

Post Implementation Ser No		
Serial Number	Model	Date
PA122CP24-227546, PA122CP22-227552		23-Sep-10

Serial Number	Model	Date

Additional Information

For all versions of PA122-CP and PA202-CP remove AL6912 CLAMP IDC HEADER A&H from the front edge of the main harness only.

003-497 MAIN ASSY PA 122-CP – Remove x11 AL6912 CLAMP IDC HEADER A&H (see attached photos)

003-499 MAIN ASSY PA 202-CP – Remove x19 AL6912 CLAMP IDC HEADER A&H (same as PA122 , plus additional inputs)

