



# ALLEN & HEATH

Released Engineering Change Note

## REC� 2701 XB-10

**Master PCB R57 change for reliability.**

**Existing resistor can go open circuit if under load and turned on and off multiple times.**

**XB-10 master assembly 004-323, AG8209 Iss2, Change R57 from AC3036 (47R) to AC6009 (47R TF)**

**Implemented date:** \_\_\_\_\_

**Serial number:** XB10X-342821

REC� is advisory.  
REC� is not a recall.  
REC� is at the discretion of the engineer.

Engineering Change Notifications are published internally as EC�.  
Changes that may affect engineers outside of Allen & Heath are published as Released Engineering Change Notes. (REC�)

**RECN 0000**

**Product: zzzz**

**Description/Title**

zzzz

**Reason**

zzzz

**Implemented date: — —**

**Serial number: — —**

**Details**